



## **CERTIFIED TEST, ADJUST AND BALANCE REPORT**

**REPORT NO. 7783B**

**PROJECT**

**ASSISSI Aged Care Centre  
230 Rosanna Road  
Rosanna Victoria  
Stage 2**

**CLIENT:**

**J.B.K Air Concitioning  
PO Box 5126  
Mordialloc Victoria 3195**

**DESIGN ENGINEER**

**Waterman AHW (Vic) Pty Ltd  
60 Park Street  
South Melbourne Victoria 3205**

**DATE: 8/04/14**

**SIGNED:**

**Russell Warry**



## CERTIFICATION

PROJECT

ASSISSI Aged Care Centre

THE DATA PRESENTED IN THIS REPORT IS A RECORD OF SYSTEM MEASUREMENTS AND FINAL ADJUSTMENTS THAT HAVE BEEN OBTAINED IN ACCORDANCE WITH THE CURRENT EDITION OF THE NEBB *PROCEDURAL STANDARDS FOR TESTING, ADJUSTING AND BALANCING OF ENVIRONMENTAL SYSTEMS*. ANY VARIANCES FROM DESIGN QUANTITIES, WHICH EXCEED NEBB TOLERANCES, ARE NOTED IN THE TEST-ADJUST-BALANCE REPORT PROJECT SUMMARY.

SUBMITTED & CERTIFIED BY:

ROSS MASON

NEBB CERTIFIED TAB FIRM NAME

COMMISSION AIR

CERTIFICATION NO. 3535 CERTIFICATION EXPIRATION DATE 31/03/2015

REPORT DATE 8/04/2014



NEBB QUALIFIED TAB SUPERVISOR NAME

ROSS MASON

NEBB QUALIFIED TAB SUPERVISOR

SIGNATURE

## TEST SHEET OUTLET

CONTRACT NO:	7783B		
PROJECT NAME:	ASSISSI Aged Care Centre		
DATE OF TEST	4/08/2014		
SYSTEM	Toilet Exhaust Fan No 59		
INSTRUMENT USED	Instant Anemometer & Hood No 1		
INSTRUMENT S/N	T52751234012	DUCT SKETCH DWG	M102

[illegible]

**NOTES:**

Tested by:

S.F

Checked by:

R.W

CONTRACT NO:	7783B
PROJECT NAME:	ASSISSI Aged Care Centre
DATE OF TEST	4/08/2014
SYSTEM	Heating Hot Water
LOCATION	Stage 2
INSTRUMENT USED	TA Scope 02-202

**NOTES:**

Tested by:

Checked by:

7-1 Rev May 2011

## INSTRUMENT CALIBRATION DETAILS

CONTRACT NO.	7783B
PROJECT NAME	ASSISSI Aged Care Centre
DATE OF TEST	8/04/2014

[illegible]

**NOTES:**

Tested by: S.F

Checked by: R.W