

Electrical Inspections Victoria  
Body Protected area RCD Test Sheet



Date: 25/06/2014  
Site Address: 230 Rosanna Road Rosanna

Room:- Medical Centre  
RCD name:- RCD 1 Circuit details:- DB1 C/B 81

	Results	
Ramp test:-	7	mA
1/2 x 0°	No trip - pass	mS
1/2 x 180°	No trip - pass	mS
1 x 0°	18	mS
1 x 180°	8	mS
5 x 0°	18	mS
5 x 180°	8	mS

Equipment connected  
Double outlet/s:- 4  
Single outlet/s:- nil  
Other:- nil

Room:- Cleaner  
RCD name:- Cleaner Circuit details:- DB 1 C/B 83

	Results	
Ramp test:-	7	mA
1/2 x 0°	No trip - pass	mS
1/2 x 180°	No trip - pass	mS
1 x 0°	19	mS
1 x 180°	9	mS
5 x 0°	19	mS
5 x 180°	9	mS

Equipment connected  
Double outlet/s:- 1  
Single outlet/s:- Nil  
Other:- Nil

Room:- Adjacent area  
RCD name:- Adjacent area Circuit details:- DB1 C/B 85

	Results	
Ramp test:-	9	mA
1/2 x 0°	No trip - pass	mS
1/2 x 180°	No trip - pass	mS
1 x 0°	19	mS
1 x 180°	9	mS
5 x 0°	19	mS
5 x 180°	9	mS

Equipment connected  
Double outlet/s:- 5  
Single outlet/s:- nil  
Other:- nil

Note:- Ramp test must operate RCD between 4.5 - 10.5 mA  
RCD tripping time to not exceed 40mS.